## **Illinois Coal Industry Significant Dates**

The following is a listing of important dates in the Illinois coal industry broken into 3 categories: Mine Disasters, Regulatory History and Landmarks in Illinois Coal Mining History. The majority of the events have a website listed which serves as a starting point for further investigation.

## Mine Disasters

1883	On February 16 <sup>th</sup> at Wilmington Coal Mining & Manufacturing Company, Diamond Mine, there were 69 miners that drown when mine flooded. http://www.ccpld.org/coalmining/coalcity/coalcity.htm
1905	On April 3 <sup>rd</sup> at Zeigler Coal Company, 47 miners were killed in an explosion and three died from asphyxiation while conducting rescue operations. <a href="http://www.zeigleril.com/pages/zighist.htm">http://www.zeigleril.com/pages/zighist.htm</a>
1909	November 13 <sup>th</sup> at St. Paul Coal Company, Mine #2 (also known as the Cherry Mine Disaster) 259 miners died in the mine fire. <a href="http://www.illinoislaborhistory.org/resources/articles.htm">http://www.illinoislaborhistory.org/resources/articles.htm</a>
1914	On October 27 <sup>th</sup> at the Franklin Coal & Coke Mine #1, 52 miners died in a gas explosion. http:// genealogytrails.com/ill/ <b>franklin</b> /1914royalton <b>mine</b> .html
1932	On December 24 <sup>th</sup> , Moweaqua Coal Company had 54 miners die in a gas explosion. <a href="http://www.illinoislaborhistory.org/resources/articles.htm">http://www.illinoislaborhistory.org/resources/articles.htm</a>
1947	On March 25 <sup>th</sup> there were 111 miners that died in coal dust explosion at Centralia Coal Company #5. <a href="http://www.illinoislaborhistory.org/resources/articles.htm">http://www.illinoislaborhistory.org/resources/articles.htm</a>
1951	On December 21 <sup>st</sup> 119 miners died in gas explosion at the Orient #2, West Frankfort, owned by the Chicago, Wilmington and Franklin Coal Company, <a href="http://www.usmra.com/saxsewell/orient.htm">http://www.usmra.com/saxsewell/orient.htm</a>

## Regulatory History

1883	The Bureau of Mines and Minerals was created, which had authority to inspect the state's coal mines. <a href="http://dnr.state.il.us/mines/">http://dnr.state.il.us/mines/</a>
1890	United Mine Workers of America was formed. It continues the fight for safe workplaces, good wages and benefits, and fair representation. <a href="http://www.umwa.org/homepage.shtml">http://www.umwa.org/homepage.shtml</a>
1891	Congress passed the first federal statute governing mine safety. The Federal Coal Mine Safety Act established ventilation requirements and prohibited operators from employing children less than 12 years of age. <a href="http://www.msha.gov/MSHAINFO/MSHAINF2.HTM">http://www.msha.gov/MSHAINFO/MSHAINF2.HTM</a>
1910	Legislation was passed that provided for the creation of mine rescue stations. This act was in response to the mine fire at the St. Paul Coal Company, Mine #2 that claimed the lives of 259 miners. <a href="http://www.osh.netnam.vn/html/coal_mines/mines_rescue.htm">http://www.osh.netnam.vn/html/coal_mines/mines_rescue.htm</a>
1917	Civil Administrative Code established the Department of Mines and Minerals, which had the powers to regulate the state's growing coal industry. <a href="http://dnr.state.il.us/mines/">http://dnr.state.il.us/mines/</a>
1948	Following the Centralia Mine disaster, legislation was adopted that created a laboratory to analyze mine air and mine dust. The first analytical laboratory was established on the campus of the University of Illinois. <a href="http://www.msha.gov/Accident_Prevention/ideas/airchange.htm">http://www.msha.gov/Accident_Prevention/ideas/airchange.htm</a>
1952	The Federal Coal Mine Safety Act gave mine inspectors power to enforce the laws on any mine that did not meet the standards of the Safety Act. <a href="https://www.msha.gov/mshainfo/mshainf2.htm">www.msha.gov/mshainfo/mshainf2.htm</a>
1962	On January 1 <sup>st</sup> , the first state laws regulating reclamation at Illinois surface coal mines became in effect. <a href="http://dnr.state.il.us/mines/education/indus3.htm">http://dnr.state.il.us/mines/education/indus3.htm</a>
1967	Air Quality Act would improve air quality and implement emission limitations. <a href="http://wps.prenhall.com/wps/media/objects/751/769950/Documents_Library/airquality.htm">http://wps.prenhall.com/wps/media/objects/751/769950/Documents_Library/airquality.htm</a>
1969	Mine Health and Safety Act creates MSHA enforcement. As a result, the safety standards for all coal mines were strengthened and health standards were adopted. <a href="http://www.msha.gov/MSHAINFO/MSHAINF2.HTM">http://www.msha.gov/MSHAINFO/MSHAINF2.HTM</a>

1970	Clean Air Act limits how much of a pollutant can be in the air anywhere in the United States to curb acid raid, urban air pollution and toxic air emissions <a href="http://www.nsc.org/ehc/mobile/acback.htm">http://www.nsc.org/ehc/mobile/acback.htm</a>
1977	Surface Mining Control and Reclamation Act protects society and environment from adverse effects of surface coal mining operations. <a href="http://ipl.unm.edu/cwl/fedbook/smcra.html">http://ipl.unm.edu/cwl/fedbook/smcra.html</a>
1977	Federal Mine Safety and Health Act states all underground mines are inspected four times a year and surface mines twice annually. <a href="http://www.dol.gov/asp/programs/guide/msha.htm">http://www.dol.gov/asp/programs/guide/msha.htm</a>
1979	On July 1 <sup>st</sup> , new laws were enacted providing mine subsidence insurance to homeowners providing coverage against damage from mine subsidence due to long abandoned coal mines. <a href="http://www.imsif.com/mine.htm">http://www.imsif.com/mine.htm</a>
1990	Clean Air Act Amendments (CAAA) set emission standards on existing fossil-fueled gereating units, a national permits program and a stepped-up enforcement program. <a href="http://www.ametsoc.org/sloan/cleanair/cleanairlegisl.html">http://www.ametsoc.org/sloan/cleanair/cleanairlegisl.html</a>
1990	National Ambient Air Quality Standards established standards for each of the criteria pollutants – sulfur dioxide (SO2) nitrogen oxide (NOx) and particulate matter (PM) to determine "attainment" and Nonattainment" areas in terms of air quality standards.
1995	Phase 1 of Acid Rain Program (ARP)requires 263 of the largest, dirtiest generating units to reduce SO2, NOx and particulate matter (PM).
1998	Emission Targets for 21 states and District of Columbia – Set NOx emission targets for each state
2000	Phase II of Acid Rain Program – extends ARP to every fossil-fueled plant greater than 25 MW.
2005	Clean Air Interstate Rule established three separate cap and trade programs for reducation of SO2, PM2.5 and NOx to reduce ozone formation.
2006	The Federal Mine Improvement and New Emergency Response (MINER) Act improves mine safety by increasing training, upgrading mining standars, improving mine emergency response, and requiring enshance technology underground for post-diaster communications, refute chambers and caches of emergency air.

## http://www.msha.gov/MinerAct

	http://www.msha.gov/MinerAct	
2006	IL Mine Safety Bill requires installation of wireless communication devices, clearly marked escape routes, and stricter certification standards for supervisors and independent contractors. <a href="http://dnr.state.il.us/mines/ommActs.htm">http://dnr.state.il.us/mines/ommActs.htm</a>	
2008	Illinois Polution Control Board (IPCB) Mine Related Water Pollution Regulations – Part 401-407 ammended to outline state and NPDES permits and requiremens for water quality	
2009	IPCB Emission Standards and Limitations for Stationry Sources – Part 212, 214-220, 223, 225 amended to outlinerequirements for visible particulate matter, sulfur, organic material, carbon monoxide, nitrogen oxides, nonmethane organic compounds, and control of emissions from large combustion sources.	
2009	IPCB Waste Disposal Regulations outlines alternative standards for coal comusion power generating facilities' waste landfills.	
2010	Mandatory Reporting of Greenhouse Gases requires reporting of greenhouse gas (GHG) emissions from all sectors of the economy.	
Landmarks in Illinois Coal Mining History		
1673	French explorers Father Jacques Marquette and Louis Joliet report seeing coal along the banks of the Illinois River near Ottawa. <a href="http://www.eslarp.uiuc.edu/ibex/archive/vignettes/frenchconnection.htm">http://www.eslarp.uiuc.edu/ibex/archive/vignettes/frenchconnection.htm</a>	
1810	The first commercial sale of coal from Illinois coal mine. Small drift mine along the banks of Big Muddy River near Murphysboro. <a href="http://www.coaleducation.org/lessons/sec/Illinois/safil.htm">http://www.coaleducation.org/lessons/sec/Illinois/safil.htm</a>	
1832	The first coal mining reported in Peoria County.  Peoria Journal Star, "More than 300 years of digging for coal in Illinois"	
1833	The first official recording of annual coal production indicated 6,000 tons were mined.	

First railroad built with the purpose of shipping coal was by a company organized by Governor Reynolds and connected the mines along the bluffs of the Mississippi River in St. Clair County with a point opposite St. Louis, MO.

<a href="http://www.lib.niu.edu/ipo/ihy020444.html">http://www.lib.niu.edu/ipo/ihy020444.html</a>

http://www.illinoisbiz.biz/coal/pdf/EIA\_State.pdf

1855	Shaft mining began after completion of the Illinois Central railroad, at DuQuoin in Perry County.  Peoria Journal Star, "More than 300 years of digging for coal in Illinois"
1861	The American Miners Association is organized in Belleville, IL and becomes the first miner's union to extend beyond one state. The Association became inactive after 1868. <a href="http://www.ilir.uiuc.edu/LII/history.html">http://www.ilir.uiuc.edu/LII/history.html</a> <a href="http://www.ilir.uiuc.edu/lii/chronlog.html">http://www.ilir.uiuc.edu/lii/chronlog.html</a>
1866	Strip mining began near Danville, Illinois, when horse-drawn plows and scrapers were used to remove overburden so the coal could be dug and hauled away in wheelbarrows and carts. <a href="http://dnr.state.il.us/orep/c2000/assessments/vermilion/mining.htm">http://dnr.state.il.us/orep/c2000/assessments/vermilion/mining.htm</a>
1870	The second bituminous coal washery (for washing and cleaning mined coal) in the United States was erected in East St. Louis.
1875	Coke replaces charcoal as the chief fuel for iron blast furnaces.
1885	The first year mechanical stripping equipment, other than horses and scoops, was used.
1887	The first underground electric mine locomotive was used in an Illinois coal mine to move loaded coal cars.
1890	United Mine Workers of America led the struggle to establish collective bargaining in American industrial life. <a href="http://www.lib.niu.edu/ipo/ihy971218.html">http://www.lib.niu.edu/ipo/ihy971218.html</a>
1896	Steel timbering is used for the first time at the shaft mine of the Spring Valley Coal Company, where 400 feet of openings are timbered with 15-inch beams.
1898	October 12 <sup>th</sup> - Battle of Virden The Chicago-Virden Coal Company attempted to break the strike by bringing in African-American miners from Alabama. Seven miners and five coal company guards were killed and scores wounded in what is recognized as a landmark event in the history of the labor movement in the United States. As a result, October 12th was declared Miner's Day. <a href="http://www.illinoislaborhistory.org/resources/articles.htm">http://www.illinoislaborhistory.org/resources/articles.htm</a>
1899	Union Miners Cemetery constructed in Mount Olive Illinois. The local UMWA union purchased a one-acre site and the bodies of the miners killed during the Battle of Virden were moved from the town cemetery and laid to rest in the new Union Miners Cemetery. Mother Jones, the

	legendary UMWA organizer, and "General" Alexander Bradley, who incited Illinois miners to join a nationwide strike called by the UMWA on July 4, 1897, are buried there. <a href="http://www.illinoislaborhistory.org/resources/articles.htm">http://www.illinoislaborhistory.org/resources/articles.htm</a>
1901	Mother Jones became involved in the struggles of coal miners and became an organizer for the United Mine Workers. <a href="http://www.illinoislaborhistory.org/resources/articles.htm">http://www.illinoislaborhistory.org/resources/articles.htm</a>
1911	The first state operated mine rescue stations were opened in LaSalle, Springfield and Benton.
1911	Three mine rescue railroad cars were commissioned for use at the state's three mine rescue stations. These rescue cars were furnished and equipped to respond to a mine emergency.
1912	The fist self-contained breathing apparatus for mine rescue operations is used.
1913	First loading of railroad cars in a strip pit.
1920	John L. Lewis became president of the UMWA. <a href="http://www.umwa.org/">http://www.umwa.org/</a>
1921	The first electrically operated coal shovel was used at the Black Servant Mine near Elkville.
1922	The UMWA goes on a nationwide strike and coal mining effectively ceased across the country.
1922	Union sympathizers murder 21 strike breakers at a strip mine in Herrin. <a href="http://www.lib.niu.edu/2001/ihy010235.html">http://www.lib.niu.edu/2001/ihy010235.html</a>
1923	Largest mining employment in Illinois history at 103,566 workers.
1928	The Assumption Coal Company, the state's deepest underground coal mine at 1,004 feet, closes after 31 years of operations.
1932	The Progressive Miners of America (PMA) was organized in Gillespie, IL by Illinois miners who were dissatisfied by the UMWA leadership of John L. Lewis. Lewis had sided with coal operators and subverted a contract referendum which reduced a miner's daily wage from \$6.10 to \$5.00. <a href="http://en.wikepedia.org/wiki/Progressive_Mine_Workers">http://en.wikepedia.org/wiki/Progressive_Mine_Workers</a> <a href="http://gillespieil.com/gillespie/pmwa">http://gillespieil.com/gillespie/pmwa</a>
1936	The first trackless means of hauling coal was used in the Blue Bird Coal Company #5 mine in southern Illinois.

1936	On October 10 <sup>th</sup> , a dedication to the Mother Jones monument was located in the Union Miner's Cemetery, Mt. Olive, Illinois. <a href="http://www.illinoislaborhistory.org/resources/articles.htm">http://www.illinoislaborhistory.org/resources/articles.htm</a>
1937	The shuttle car is introduced by Joy Manufacturing Company.
1938	Reclamation of surface mined lands was started on a voluntary basis by mining companies. This consisted entirely of tree planting.
1948	The continuous miner is introduced.
1955	The rail industry virtually completes its switch from coal-fired to diesel locomotives.
1961	Coal becomes the major fuel used by electric utilities to generate electricity.
1981	Illinois recorded the first fatality-free year in mining history.
1991-2010	15 Illinois power plants switched to lower sulfur Western coal, resulting in a loss of 50.1 million tons of Illinois coal sales annually.